SCHAPENDONK
AUTOMOBIELBEDRIJF

Vehicle datasheet

HYUNDAI I 10 2009

Vehicle	
License plate	8XHB75
VIN	MALAM51BP9M256412
Make	HYUNDAI
Model	I 10
Year	2009
Colour	Rood
Mileage	131.441 km
Fuel type	Benzine
Transmission	Automatic
First registration date	11-03-2009
APK (roadworthiness) valid until	19-03-2027
Euro emission class	Euro 4
CO2 emissions	139 g/km
Power	49 kW
Number of seats	5
Origin	Onbekend
Country of registration	Netherlands
Country of origin	Germany (unsure)
Number of owners	N/A
Previous commercial use	Not in commercial use
VAT type	Margin (not deductible)

Findings	
Did the air conditioning work at different temperatures?	N/A

Tyres and brakes	
Front left wheel: rim type	Steel with wheel cap
Front right wheel: brake condition	More than 50%
Front right wheel: rim type	Steel with wheel cap
Rear left wheel: brake condition	More than 50%
Rear left wheel: rim type	Steel with wheel cap

Tyres and brakes	
Rear right wheel: brake condition	More than 50%
Rear right wheel: rim type	Steel with wheel cap

Equipment	
Airbag	Not available
ABS	No
ESP	No
Power windows	Not available
Air conditioning	Not available
Particulate filter	No

Other information	
Metallic	No
Number of keys	2

Service	
Service book	Paper service book available
Last service date (mm/yyyy)	03/2024
Mileage at last service	82723 km
Drive belt replaced?	Yes
Drive belt replacement date (mm/yyyy)	02/2020
Mileage at drive belt replacement	50667 km
Is the engine original?	Yes
Is the car roadworthy?	Yes

Remarks	
Remark 1	Paint thickness meter was not available, therefore it is unclear if there is an accident history.

Information as known on 22-11-2026. No rights can be derived from this datasheet; the buyer remains responsible for verifying the information.