SCHAPENDONK
AUTOMOBIELBEDRIJF

Vehicle datasheet

Opel Grandland damaged 2025

Vehicle	
VIN	VXKKAHPY7S6057275
Make	Opel
Model	Grandland damaged
Year	2025
Colour	Zilver
Mileage	31.920 km
Fuel type	Hybride
Transmission	Automatic
First registration date	24-11-2025
Number of seats	2
Country of registration	France
Country of origin	France
Number of owners	1
Previous commercial use	Not in commercial use
VAT type	VAT (deductible)

Test drive	
Was the test drive performed?	No
Why was the test drive not performed?	Car in dangerous condition

Accidents	
Areas with accident	Front, Exterior left, Exterior right, Rear, Roof
Reasons for the accident (for every area)	One or more panels are severely deformed, resulting in significant cosmetic damage, Other

Equipment	
Audio system	Present (factory equipment), In navigation system
Air conditioning	Present (factory equipment), Automatic
Heated seats	Not available
Particulate filter	Yes
Park Distance Control	Not original
Park Distance Control: options	Front and rear

Equipment	
Navigation system	Big

Other information	
Number of seats	5

Service	
Service book appointments	None
Drive belt replaced?	No
MOT expiry (mm/yyyy)	11/2029
Is the engine original?	Yes
Is the car roadworthy?	No
Can the car be rolled?	Yes

Remarks	
Remark 1	We have not performed a technical inspection. The findings included in this description are only an indication. The buyer is responsible for checking whether they are complete and correct.
Remark 2	This is a VAT-applicable vehicle; bids are exclusive of VAT. The winning bid will be subject to the addition of VAT.
Remark 3	The vehicle documents are complete and suitable for re-registration.

Information as known on 22-11-2026. No rights can be derived from this datasheet; the buyer remains responsible for verifying the information.