SCHAPENDONK
AUTOMOBIELBEDRIJF

Vehicle datasheet

Daihatsu Feroza 1994

Vehicle	
VIN	JDA00F30000073740
Make	Daihatsu
Model	Feroza
Year	1994
Colour	Groen
Mileage	48.657 km
Fuel type	Benzine
Transmission	Manual
First registration date	03-02-1994
Power	63 kW
Country of registration	Belgium
Country of origin	Belgium
Number of owners	N/A
Previous commercial use	Not in commercial use
VAT type	Margin (not deductible)

Mileage	
Current mileage	48657 km
Suspicion that the mileage was manipulated	Yes
Reasons	Database mileage conflicting with current mileage (Carvertical etc)

Test drive	
Type of test drive	Only on property
Why was the test drive done on own property?	Car in dangerous condition

Findings	
Was the braking behaviour normal?	No
Reasons	Poor braking
Did the air conditioning work at different temperatures?	N/A

Tyres and brakes	
Front left wheel: tread depth	2 mm
Front left wheel: brake condition	Poor brake pattern
Front left wheel: rim type	Steel
Front right wheel: tread depth	2 mm
Front right wheel: brake condition	Poor brake pattern
Front right wheel: rim type	Steel
Rear left wheel: tread depth	2 mm
Rear left wheel: brake condition	Poor brake pattern
Rear left wheel: rim type	Steel
Rear right wheel: tread depth	2 mm
Rear right wheel: brake condition	Poor brake pattern
Rear right wheel: rim type	Steel

Equipment	
Airbag	Not available
ABS	No
Audio system	Not available
On-board computer	Not available
ESP	No
Power windows	Not available
Air conditioning	Not available
Immobilizer	No
Tow bar	Fixed (not original)
Particulate filter	No

Other information	
Number of seats	4

Service	
Service book appointments	None
Drive belt replaced?	No
MOT expiry (mm/yyyy)	12/2016
Is the engine original?	Yes
Is the car roadworthy?	No
Can the car be rolled?	Yes

Remarks	
Remark 1	The odometer only has 5 digits, that is why the actual mileage is uncertain.

Remarks	
Remark 2	We have not performed a technical inspection. The findings included in this description are only an indication. The buyer is responsible for checking whether they are complete and correct.
Remark 3	The vehicle should be viewed as a restoration project or a donor vehicle.
Remark 4	This is a margin vehicle; VAT does not apply.
Remark 5	The vehicle documents are complete and suitable for re-registration.

Information as known on 22-11-2026. No rights can be derived from this datasheet; the buyer remains responsible for verifying the information.