SCHAPENDONK
AUTOMOBIELBEDRIJF

Vehicle datasheet

Toyota Celica 1990

Vehicle	
VIN	JT164ATJ000009208
Make	Toyota
Model	Celica
Year	1990
Colour	Grijs
Mileage	315.690 km
Fuel type	Benzine
Transmission	Manual
First registration date	09-01-1990
Power	78 kW
Number of seats	2
Country of registration	Belgium
Country of origin	Belgium
Number of owners	N/A
Previous commercial use	Not in commercial use
VAT type	Margin (not deductible)

Mileage	
Suspicion that the mileage was manipulated	No

Test drive	
Type of test drive	Only on property
Why was the test drive done on own property?	Car in dangerous condition

Findings	
Was the engine behaviour normal (standing and driving)?	No
When?	While standing still, While driving
Problems	Heavy smoke, No power
Did the air conditioning work at different temperatures?	N/A

Tyres and brakes	
Front left wheel: tread depth	2 mm
Front left wheel: brake condition	Less than 50%
Front left wheel: rim type	Aluminium - third party
Front right wheel: tread depth	2 mm
Front right wheel: rim type	Aluminium - third party
Rear left wheel: tread depth	2 mm
Rear left wheel: rim type	Aluminium - third party
Rear right wheel: tread depth	2 mm
Rear right wheel: rim type	Aluminium - third party

Equipment	
Airbag	Not available
ABS	No
Audio system	Not available
On-board computer	Not available
ESP	No
Power windows	Not available
Air conditioning	Not available
Immobilizer	No
Particulate filter	No

Other information	
Number of seats	4

Service	
Service book	Yes, digital
Drive belt replaced?	Yes
Drive belt replacement date (mm/yyyy)	06/2025
Mileage at drive belt replacement	312610 km
MOT expiry (mm/yyyy)	03/2026
Is the engine original?	Yes
Is the car roadworthy?	No
Can the car be rolled?	Yes

Remarks	
Remark 1	Mileage report shows irregularities. Given the course of registrations, we believe that these are incorrect registrations. We therefore assess the mileage of the vehicle as credible. A photo of the report has been added so that the buyer can judge for himself.

Remarks	
Remark 2	We have not performed a technical inspection. The findings included in this description are only an indication. The buyer is responsible for checking whether they are complete and correct.
Remark 3	The vehicle should be viewed as a restoration project or a donor vehicle.
Remark 4	This is a margin vehicle; VAT does not apply.
Remark 5	The vehicle documents are complete and suitable for re-registration.
Remark 6	If desired, a forklift is available on site to load the vehicle for you for a fee of €50.

Information as known on 22-11-2026. No rights can be derived from this datasheet; the buyer remains responsible for verifying the information.